

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 4/30/2025	Time: 10:41 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.	Corp ID: 525625	
Address of School Corporation: PO Box 550		
City: Converse	Zip: 46919	County Number: 52
VIN: 4UZABRDT4GCGS9744	License Number: 1119	Bus Number: 11
Make of Body: Thomas Built Buses, Inc.	Year: 2014	Make of Chassis: Freightliner
Year: 2016	Mileage: 121867	Year: 2016
Bus Type: C		
Inspection Status: R	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.