

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 5/1/2025	Time: 9:38 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.	Corp ID: 525625	
Address of School Corporation: PO Box 550		
City: Converse	Zip: 46919	County Number: 52
VIN: 1BAKGCEA3JF337231	License Number: 19630	Bus Number: 9
Make of Body: Blue Bird Corporation	Year: 2016	Make of Chassis: Blue Bird Corporation
Year: 2018	Mileage: 127305	PE: 7018
Bus Type: C	Inspected By: Randy McPike	
Inspection Status: R		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
64-1-4	Any front turn signal does not function properly
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.