

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 5/1/2025	Time: 10:18 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.	Corp ID: 525625	
Address of School Corporation: PO Box 550		
City: Converse	Zip: 46919	County Number: 52
VIN: 4UZABRDT6HCHS6056	License Number: 11559	Bus Number: 23
Make of Body: Thomas Built Buses, Inc.	Year: 2016	Make of Chassis: Freightliner
Year: 2017	Mileage: 170680	PE: 7018
Bus Type: C		
Inspection Status: R	Inspected By: Randy McPike	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.