

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 5/1/2025	Time: 10:33 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.	Corp ID: 525625	
Address of School Corporation: PO Box 550		
City: Converse	Zip: 46919	County Number: 52
VIN: 1BAKGCEA5JF337232	License Number: 14527	Bus Number: 27
Make of Body: Blue Bird Corporation	Year: 2016	Make of Chassis: Blue Bird Corporation
Bus Type: C	Mileage: 105287	Year: 2018
Inspection Status: R	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
17-1-1	Any dome light is inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.