REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	5/1/2025	**Time:**	3:20 PM
Name of School Corporation:	SOUTHWEST DUBOIS SCH. CORP.			**Corp ID:**	192110
Address of School Corporation:	105 W Sunset Dr				
City:	Huntingburg	**Zip:**	47542	**County Number:**	19
VIN:	4DRBUAANXDB312295	**License Number:**	4981	**Bus Number:**	17
Make of Body:	IC Corporation **Year:** 2012	**Make of Chassis:**	IC Corporation	**Year:**	2013
Bus Type:	C	**Mileage:**	59037		
Inspection Status:	O	**Inspected By:**	Philip Lubbers	**PE:**	7703

Violations - Rejected

Inspection Code	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	Description
11-2-2	A bumper does not meet manufactures specifications

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.