REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/6/2025	**Time:**	10:47 AM
Name of School Corporation:	NORTH PUTNAM COMMUNITY SCHOOLS			**Corp ID:**	676715
Address of School Corporation:	Box 169				
City:	Bainbridge	**Zip:**	46105	**County Number:**	67
VIN:	4DRBUC8N5JB048531	**License Number:**	17925	**Bus Number:**	2418
Make of Body:	IC Corporation **Year:** 2017	**Make of Chassis:**	IC Corporation	**Year:**	2018
Bus Type:	C	**Mileage:**	107788		
Inspection Status:	O	**Inspected By:**	Byron Goodman	**PE:**	7008

Violations - Rejected

Inspection Code	Description
11-1-7	See Notes: Any defect inspector deems a violation not listed
34-1-5	See Notes: Any defect inspector deems a violation not listed
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.