

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/6/2025	Time:	1:29 PM		
Name of School Corporation:	NORTHWESTERN SCHOOL CORP.			Corp ID:	343470		
Address of School Corporation:	3075 N Washington St						
City:	Kokomo	Zip:	46901	County Number:	34		
VIN:	4UZABRDT5GCHF6952		License Number:	10425	Bus Number:	8	
Make of Body:	Thomas Built Buses, Inc.	Year:	2015	Make of Chassis:	Freightliner	Year:	2016
Bus Type:	C			Mileage:	168118		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
64-1-4	Any front turn signal does not function properly
68-1-1	Washers do not function properly in any manner
33-1-2	The grill is missing
34-1-1	Any headlight is inoperative
34-1-5	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
25-2-2	Reflective glass is cracked, broken, or missing
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.