

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/12/2025	Time:	9:46 AM
Name of School Corporation:	SOUTHWESTERN CON SCH SHELBY CO	Corp ID:	737360		
Address of School Corporation:	3406 W 600 S				
City:	Shelbyville	Zip:	46176	County Number:	73
VIN:	1GB3G2BG8E1112601	License Number:	22383	Bus Number:	19
Make of Body:	Collins Bus Corporation	Year:	2013	Make of Chassis:	Chevrolet
Bus Type:	A2	Mileage:	129242	Year:	2014
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
33-1-1	The grill has any exposed edges that may cause injury
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
63-1-10	Any mud flaps or other devices are loose

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.