REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	5/13/2025	**Time:**	9:35 AM
Name of School Corporation:	PRIMROSE WEST CARMEL			**Corp ID:**	1100382
Address of School Corporation:	3746 W. 96th st				
City:	Carmel	**Zip:**	46032	**County Number:**	29
VIN:	1GBHG31C181231394	**License Number:**	B115K	**Bus Number:**	A1
Make of Body:	Chevrolet **Year:** 2008	**Make of Chassis:**	Collins Bus Corporation	**Year:**	2008
Bus Type:	A1	**Mileage:**	73019		
Inspection Status:	O	**Inspected By:**	Jeff Stone	**PE:**	8184

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
8-2-5	There is brake fluid leaking at any point

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**