

## REPORT OF SCHOOL BUS INSPECTION

|                                |                          |                 |                |                  |                          |
|--------------------------------|--------------------------|-----------------|----------------|------------------|--------------------------|
| Type of Inspection:            | Annual                   | Date:           | 5/14/2025      | Time:            | 11:24 AM                 |
| Name of School Corporation:    | BAUGO COMMUNITY SCHOOLS  |                 |                | Corp ID:         | 202260                   |
| Address of School Corporation: | 29125 CR 22 W            |                 |                |                  |                          |
| City:                          | Elkhart                  | Zip:            | 46517          | County Number:   | 20                       |
| VIN:                           | 1T7Y74D28J1130981        | License Number: | 21716          | Bus Number:      | 16                       |
| Make of Body:                  | Thomas Built Buses, Inc. | Year:           | 2017           | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type:                      | D                        |                 |                | Mileage:         | 66185                    |
| Inspection Status:             | O                        | Inspected By:   | Joseph Hartman | PE:              | 7257                     |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 2-1-4                  | LED type lights have 25% or more of the pixels inoperable in any one light   |
| 64-1-4                 | Any front turn signal does not function properly   |
| 64-1-6                 | See Notes: Any defect inspector deems a violation not listed   |
| 28-1-4                 | The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction. |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>                                   |
|------------------------|--|
| 64-2-1                 | Any rear turn signal does not function properly      |
| 65-2-5                 | LED lights have 50% or more of the pixels inoperable |

### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.