

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/14/2025	Time:	12:18 PM		
Name of School Corporation:	BAUGO COMMUNITY SCHOOLS			Corp ID:	202260		
Address of School Corporation:	29125 CR 22 W						
City:	Elkhart	Zip:	46517	County Number:	20		
VIN:	1GB3GSBG8J1254294		License Number:	33498	Bus Number:	20	
Make of Body:	Thomas Built Buses, Inc.	Year:	2018	Make of Chassis:	Chevrolet	Year:	2019
Bus Type:	A2			Mileage:	57353		
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
35-1-1	A heater motor is not operating properly
60-1-1	Sun visor is missing, cracked or broken

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.