

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/16/2025	Time:	2:10 PM		
Name of School Corporation:	ELKHART COMMUNITY SCHOOLS			Corp ID:	202305		
Address of School Corporation:	2720 California Rd						
City:	Elkhart	Zip:	46514	County Number:	20		
VIN:	1T7Y74D21S1218370		License Number:	27123	Bus Number:	44	
Make of Body:	Thomas Built Buses, Inc.	Year:	2024	Make of Chassis:	Freightliner	Year:	2024
Bus Type:	D			Mileage:	717		
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257		

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.