

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/16/2025	Time:	2:15 PM
Name of School Corporation:	ELKHART COMMUNITY SCHOOLS	Corp ID:	202305		
Address of School Corporation:	2720 California Rd				
City:	Elkhart	Zip:	46514	County Number:	20
VIN:	4DRBUC8N8KB068998	License Number:	5783	Bus Number:	119
Make of Body:	IC Corporation	Year:	2018	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	70589	Year:	2019
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
25-2-2	Reflective glass is cracked, broken, or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.