

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 5/21/2025	Time: 9:56 AM
Name of School Corporation: ELWOOD COMMUNITY SCHOOL CORP.	Corp ID: 485280	
Address of School Corporation: 1306 N Anderson St		
City: Elwood	Zip: 46036	County Number: 48
VIN: 4DRBUSKP9CB589444	License Number: 1582	Bus Number: 7
Make of Body: IC Corporation	Year: 2011	Make of Chassis: IC Corporation
Year: 2012		
Bus Type: C	Mileage: 80242	
Inspection Status: R	Inspected By: Brandon Steffee	PE: 8247

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.