

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|-------------------------------|-----------------|------------|------------------|--------------------------|
| Type of Inspection: | Annual | Date: | 5/27/2025 | Time: | 11:24 AM |
| Name of School Corporation: | HAMILTON SOUTHEASTERN SCHOOLS | | | Corp ID: | 293005 |
| Address of School Corporation: | 13485 Cumberland Rd | | | | |
| City: | Fishers | Zip: | 46038 | County Number: | 29 |
| VIN: | 1T7Y54D26K1139220 | License Number: | 22320 | Bus Number: | 186 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2017 | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type: | D | Mileage: | 58955 | Year: | 2019 |
| Inspection Status: | R | Inspected By: | Jeff Stone | PE: | 8184 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 2-1-4 | LED type lights have 25% or more of the pixels inoperable in any one light |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.