

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/30/2025	<b>Time:</b> 11:16 AM
<b>Name of School Corporation:</b> CENTRAL NOBLE COMM SCHOOL CORP	<b>Corp ID:</b> 576055	
<b>Address of School Corporation:</b> 200 E Main St		
<b>City:</b> Albion	<b>Zip:</b> 46701	<b>County Number:</b> 57
<b>VIN:</b> 1BAKJCSA1MF372814	<b>License Number:</b> 23760	<b>Bus Number:</b> 17
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2019	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Year:</b> 2021	<b>Mileage:</b> 58098	<b>PE:</b> 7257
<b>Bus Type:</b> C	<b>Inspected By:</b> Joseph Hartman	
<b>Inspection Status:</b> R		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.