

# REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	6/2/2025	<b>Time:</b>	12:19 PM
<b>Name of School Corporation:</b>		AUXILIO SERVICES (MUNCIE)		<b>Corp ID:</b>	251807
<b>Address of School Corporation:</b>		11260 Cornell Park Dr Suite 700			
<b>City:</b>	Cincinnati	<b>Zip:</b>	45242	<b>County Number:</b>	18
<b>VIN:</b>	4UZABRDT9JCJF1840	<b>License Number:</b>	B548N	<b>Bus Number:</b>	M23
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2016	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	89490	<b>Year:</b>	2018
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Steve Spallinger	<b>PE:</b>	6921

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
68-1-1	Washers do not function properly in any manner
60-1-2	See Notes: Any defect inspector deems a violation not listed
7-1-5	See Notes: Any defect inspector deems a violation not listed

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit

## Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.