

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/2/2025	Time:	1:11 PM
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			Corp ID:	251807
Address of School Corporation:	11260 Cornell Park Dr Suite 700				
City:	Cincinnati	Zip:	45242	County Number:	18
VIN:	4DRBUC8P9JB524149			License Number:	B483N
Make of Body:	IC Corporation	Year:	2019	Make of Chassis:	IC Corporation
Bus Type:	C			Year:	2018
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.