

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 6/3/2025 Time: 11:14 AM
Name of School Corporation: AUXILIO SERVICES (MUNCIE) Corp ID: 251807
Address of School Corporation: 11260 Cornell Park Dr Suite 700
City: Cincinnati Zip: 45242 County Number: 18
VIN: 1GB3GSBG2H1249232 License Number: B472S Bus Number: M35
Make of Body: Chevrolet Year: 2017 Make of Chassis: Chevrolet Year: 2017
Bus Type: A1 Mileage: 63161
Inspection Status: O Inspected By: Steve Spallinger PE: 6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.