

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection Date: 6/3/2025 Time: 11:15 AM  
Name of School Corporation: AUXILIO SERVICES (MUNCIE) Corp ID: 251807  
Address of School Corporation: 11260 Cornell Park Dr Suite 700  
City: Cincinnati Zip: 45242 County Number: 18  
VIN: 1GB3GSBG2H1249232 License Number: B472S Bus Number: M35  
Make of Body: Chevrolet Year: 2017 Make of Chassis: Chevrolet Year: 2017  
Bus Type: A1 Mileage: 63161  
Inspection Status: O Inspected By: Steve Spallinger PE: 6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.