

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/3/2025	Time:	11:33 AM
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			Corp ID:	251807
Address of School Corporation:	11260 Cornell Park Dr Suite 700				
City:	Cincinnati	Zip:	45242	County Number:	18
VIN:	1GB3GRBG5J1321135			License Number:	B331R
Make of Body:	Thomas Built Buses, Inc.	Year:	2018	Make of Chassis:	Chevrolet
Bus Type:	A1			Year:	2018
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
49-1-1	The reflective material is placed anywhere other than on the front and rear, or both, of the bus between the warning lamps; each side beltline, seat line, or floor line or all three (3); outlining each required emergency exit; or across the rear of the bus directly above the rear bumper.

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.