

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/3/2025	Time:	12:01 PM		
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			Corp ID:	251807		
Address of School Corporation:	11260 Cornell Park Dr Suite 700						
City:	Cincinnati	Zip:	45242	County Number:	18		
VIN:	4UZABRDT7JCJF1836	License Number:	B710N	Bus Number:	M18		
Make of Body:	Thomas Built Buses, Inc.	Year:	2016	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2018
Bus Type:	C	Mileage:	80876				
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
7-1-5	See Notes: Any defect inspector deems a violation not listed
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
22-1-1	A dripping oil or fluid leak
35-1-1	A heater motor is not operating properly
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.