REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	6/3/2025	**Time:**	12:40 PM
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)				**Corp ID:**	251807
Address of School Corporation:	11260 Cornell Park Dr Suite 700					
City:	Cincinnati	**Zip:**	45242		**County Number:**	18
VIN:	1BAKGCEA1MF368630		**License Number:**	B900U	**Bus Number:**	M47
Make of Body:	Blue Bird Corporation	**Year:** 2019	**Make of Chassis:**	Blue Bird Corporation	**Year:**	2022
Bus Type:	C		**Mileage:**	57262		
Inspection Status:	R	**Inspected By:**	Steve Spallinger		**PE:**	6921

Violations - Rejected

Inspection Code	Description
50-1-2	The seat belt cutter is not secured using a positive fastening method.
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
22-1-1	A dripping oil or fluid leak
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.