

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/3/2025	Time: 12:40 PM
Name of School Corporation: AUXILIO SERVICES (MUNCIE)		Corp ID: 251807
Address of School Corporation: 11260 Cornell Park Dr Suite 700		
City: Cincinnati	Zip: 45242	County Number: 18
VIN: 1BAKGCEA1MF368630	License Number: B900U	Bus Number: M47
Make of Body: Blue Bird Corporation	Year: 2019	Make of Chassis: Blue Bird Corporation
Year: 2022	Mileage: 57262	PE: 6921
Bus Type: C	Inspected By: Steve Spallinger	
Inspection Status: R		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-2	The seat belt cutter is not secured using a positive fastening method.
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
22-1-1	A dripping oil or fluid leak
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.