

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 6/4/2025 Time: 10:54 AM
Name of School Corporation: DANVILLE COMM SCHLS. Corp ID: 323325
Address of School Corporation: 1380 W Lincoln St
City: Danville Zip: 46122 County Number: 32
VIN: 1GB3GRBG7G1187673 License Number: 37454 Bus Number: V5
Make of Body: Starcraft Year: 2016 Make of Chassis: Chevrolet Year: 2016
Bus Type: A1 Mileage: 96680
Inspection Status: O Inspected By: Byron Goodman PE: 7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.