## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Re-InspectionDate:6/10/2025Time:9:58 AMName of School Corporation:LEBANON COMMUNITY SCHOOL CORP.Corp ID:60665

Address of School Corporation: 505 Ransdell Rd

City:LebanonZip:46052County Number: 6VIN:4DRBUC8N1JB421032License Number: 18643Bus Number: 37Make of Body:IC Corporation Year: 2017Make of Chassis: IC Corporation Year: 2018

Bus Type: C Mileage: 86114

Inspection Status: O Inspected By: Joel Flores PE: 7415

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

57-1-5 Step-well light is missing or inoperative

## **Violations - Out of Service**

Inspection Code Description

7-2-4 Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.