

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 6/11/2025	<b>Time:</b> 10:17 AM
<b>Name of School Corporation:</b> UNION SCHOOL CORPORATION	<b>Corp ID:</b> 686795	
<b>Address of School Corporation:</b> 8707 W US 36		
<b>City:</b> Modoc	<b>Zip:</b> 47358	<b>County Number:</b> 68
<b>VIN:</b> 4drbuskp1bb262051	<b>License Number:</b> 7134	<b>Bus Number:</b> 5
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2009	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2009	<b>Bus Type:</b> C	<b>Mileage:</b> 113173
<b>Inspection Status:</b> O	<b>Inspected By:</b> Steve Spallinger	<b>PE:</b> 6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-2	One (1) taillight or one (1) brake light does not function
26-1-4	Not securely mounted
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
89-1-3	The strobe light is inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**