

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/11/2025	Time:	11:37 AM
Name of School Corporation:	UNION SCHOOL CORPORATION	Corp ID:	686795		
Address of School Corporation:	8707 W US 36				
City:	Modoc	Zip:	47358	County Number:	68
VIN:	1GBJG31K591154524	License Number:	80600	Bus Number:	14
Make of Body:	Collins Bus Corporation	Year:	2009	Make of Chassis:	Chevrolet
Bus Type:	A2	Mileage:	128104	Year:	2009
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.