REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	6/11/2025	**Time:**	11:37 AM
Name of School Corporation:		UNION SCHOOL CORPORATION				**Corp ID:**	686795
Address of School Corporation:		8707 W US 36					
City:	Modoc	**Zip:**	47358			**County Number:**	68
VIN:	1GBJG31K591154524			**License Number:**	80600	**Bus Number:**	14
Make of Body:	Collins Bus Corporation	**Year:**	2009	**Make of Chassis:**	Chevrolet	**Year:**	2009
Bus Type:	A2			**Mileage:**	128104		
Inspection Status:	O	**Inspected By:**	Steve Spallinger			**PE:**	6921

Violations - Rejected

Inspection Code	Description
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**