

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 6/13/2025	<b>Time:</b> 10:41 AM
<b>Name of School Corporation:</b>	NORTH VERMILLION COMM SCH CORP	<b>Corp ID:</b> 838010
<b>Address of School Corporation:</b>	5551 N Falcon Dr	
<b>City:</b> Cayuga	<b>Zip:</b> 47928	<b>County Number:</b> 83
<b>VIN:</b> 1GB3G3BG2B1175629	<b>License Number:</b> 47357	<b>Bus Number:</b> 18
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2011	<b>Make of Chassis:</b> Chevrolet <b>Year:</b> 2012
<b>Bus Type:</b>	<b>Mileage:</b> 216564	
<b>Inspection Status:</b> O	<b>Inspected By:</b> Byron Goodman	<b>PE:</b> 7008

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
10-2-2	The parking brake fails to hold the bus during the testing procedure. (Note – It is NOT a violation if the test cannot be done due to OEM design)

### Bus Type Description