REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	6/27/2025	**Time:** 11:17 AM
Name of School Corporation:	DALEVILLE COMMUNITY SCHOOLS				**Corp ID:** 181940
Address of School Corporation:	14300 W 2nd St				
City:	Daleville	**Zip:**	47334		**County Number:** 18
VIN:	4DRBUAAN4FB508106		**License Number:**	7176	**Bus Number:** 12
Make of Body:	IC Corporation	**Year:** 2014	**Make of Chassis:**	IC Corporation	**Year:** 2015
Bus Type:	C		**Mileage:**	80264	
Inspection Status:	O	**Inspected By:**	Steve Spallinger		**PE:** 6921

Violations - Rejected

Inspection Code	Description
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
46-1-2	Any seat back or bottom is loose

Violations - Out of Service

Inspection Code	Description
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.