

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/30/2025	Time: 9:07 AM
Name of School Corporation: CULVER COMMUNITY SCHOOLS CORP.	Corp ID: 505455	
Address of School Corporation: PO Box 231		
City: Culver	Zip: 46511	County Number: 50
VIN: 4DRBUC8P1LB206014	License Number: 23326	Bus Number: 18
Make of Body: IC Corporation	Year: 2019	Make of Chassis: IC Corporation
Year: 2019	Mileage: 83776	PE: 8022
Bus Type: C	Inspected By: Travis Harrold	
Inspection Status: R		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-2	Any interior protrusions have sharp edges or corners

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.