

## REPORT OF SCHOOL BUS INSPECTION

|                                |                        |               |             |                  |                |
|--------------------------------|------------------------|---------------|-------------|------------------|----------------|
| Type of Inspection:            | Annual                 | Date:         | 7/7/2025    | Time:            | 12:00 PM       |
| Name of School Corporation:    | FIRST STUDENT - INDPLS |               |             | Corp ID:         | 4981           |
| Address of School Corporation: | xxx                    |               |             |                  |                |
| City:                          | Indianapolis           | Zip:          | 46202       | County Number:   | 49             |
| VIN:                           | 4DRBUP1N0HB474428      |               |             | License Number:  | 833            |
| Make of Body:                  | IC Corporation         | Year:         | 2016        | Make of Chassis: | IC Corporation |
| Bus Type:                      | C                      |               |             | Year:            | 2017           |
| Inspection Status:             | O                      | Inspected By: | Joel Flores | PE:              | 7415           |

### Violations - Rejected

### Inspection Code Description

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 7-2-4                  | Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).     |
| 63-2-1                 | Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord  |
| 59-2-6                 | LED type lights have 50% or more pixels inoperable in one light. (NOTE: one letter in the word "STOP" equals one light.) |

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.