

## REPORT OF SCHOOL BUS INSPECTION

|                                                              |                                       |                                               |
|--------------------------------------------------------------|---------------------------------------|-----------------------------------------------|
| <b>Type of Inspection:</b> Annual                            | <b>Date:</b> 7/10/2025                | <b>Time:</b> 10:31 AM                         |
| <b>Name of School Corporation:</b> NORTH ADAMS COMM. SCHOOLS | <b>Corp ID:</b> 10025                 |                                               |
| <b>Address of School Corporation:</b>                        |                                       |                                               |
| <b>City:</b>                                                 | <b>Zip:</b>                           | <b>County Number:</b> 1                       |
| <b>VIN:</b> 1BAKF CPA9DF289822                               | <b>License Number:</b> 7202           | <b>Bus Number:</b> 9                          |
| <b>Make of Body:</b> Blue Bird Corporation                   | <b>Year:</b> 2011                     | <b>Make of Chassis:</b> Blue Bird Corporation |
| <b>Bus Type:</b> C                                           | <b>Mileage:</b> 91512                 | <b>Year:</b> 2011                             |
| <b>Inspection Status:</b> R                                  | <b>Inspected By:</b> Steve Spallinger | <b>PE:</b> 6921                               |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>           |
|------------------------|------------------------------|
| 29-1-3                 | There are holes in the floor |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.