

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 7/14/2025 **Time:** 11:40 AM
Name of School Corporation: MILLER TRANSPORTATION **Corp ID:** 49022Z
Address of School Corporation: 4045 Park 65 Dr
City: Indianapolis **Zip:** 46254 **County Number:** 49
VIN: 4DRBUC8N4JB438391 **License Number:** B426N **Bus Number:** 2022
Make of Body: IC Corporation **Year:** 2017 **Make of Chassis:** IC Corporation **Year:** 2018
Bus Type: C **Mileage:** 143569
Inspection Status: O **Inspected By:** Jeff Stone **PE:** 8184

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 11-1-7 | See Notes: Any defect inspector deems a violation not listed |
| 20-1-10 | See Notes: Any defect inspector deems a violation not listed |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 31-2-1 | Frame is deteriorated, cracked, broken or severely bent |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.