

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/30/2025	Time:	10:46 AM
Name of School Corporation:	LUTHERAN HIGH SCHOOL			Corp ID:	49C270
Address of School Corporation:	5555 S Arlington Ave				
City:	Indianapolis	Zip:	46237	County Number:	49
VIN:	1GB3G2BG9E1187310			License Number:	B183R
Make of Body:	Collins Bus Corporation	Year:	2014	Make of Chassis:	Chevrolet
Bus Type:	A1			Year:	2014
Inspection Status:	R	Inspected By:	Kyle Parton	PE:	9108

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
79-1-5	See Notes: Any defect inspector deems a violation not listed

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.