

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	8/1/2025	Time:	11:50 AM		
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			Corp ID:	251807		
Address of School Corporation:	11260 Cornell Park Dr Suite 700						
City:	Cincinnati	Zip:	45242	County Number:	18		
VIN:	4DRBUC8P6GB724480		License Number:	B516N	Bus Number:	M14	
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation	Year:	2016
Bus Type:	C			Mileage:	61605		
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
26-1-4	Not securely mounted
64-1-4	Any front turn signal does not function properly
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
62-1-2	One (1) taillight or one (1) brake light does not function

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.