REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	8/1/2025	**Time:**	12:56 PM
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)				**Corp ID:**	251807
Address of School Corporation:	11260 Cornell Park Dr Suite 700					
City:	Cincinnati	**Zip:**	45242		**County Number:**	18
VIN:	4DRBUC8P9JB524152		**License Number:**	B486N	**Bus Number:**	M7
Make of Body:	IC Corporation	**Year:** 2016	**Make of Chassis:**	IC Corporation	**Year:**	2018
Bus Type:	C		**Mileage:**	76263		
Inspection Status:	O	**Inspected By:**	Steve Spallinger		**PE:**	6921

Violations - Rejected

Inspection Code	Description
95-1-15	See Notes: Any defect inspector deems a violation not listed
26-1-4	Not securely mounted
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
68-1-1	Washers do not function properly in any manner
50-1-2	The seat belt cutter is not secured using a positive fastening method.
19-1-1	Not equipped with a driver’s seat which is securely mounted and capable of supporting the driver in a seated position

Violations - Out of Service

Inspection Code	Description
59-2-3	Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.