

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection Date: 8/4/2025 Time: 11:15 AM
Name of School Corporation: AUXILIO SERVICES (MUNCIE) Corp ID: 251807
Address of School Corporation: 11260 Cornell Park Dr Suite 700
City: Cincinnati Zip: 45242 County Number: 18
VIN: 1GB3GSBGXH1134782 License Number: B890N Bus Number: M40
Make of Body: Chevrolet Year: 2017 Make of Chassis: AmTran Year: 2017
Bus Type: A1 Mileage: 56421
Inspection Status: O Inspected By: Steve Spallinger PE: 6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
49-1-1	The reflective material is placed anywhere other than on the front and rear, or both, of the bus between the warning lamps; each side beltline, seat line, or floor line or all three (3); outlining each required emergency exit; or across the rear of the bus directly above the rear bumper.
17-1-1	Any dome light is inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.