

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 8/6/2025 **Time:** 7:47 AM
Name of School Corporation: FIRST STUDENT-GARY **Corp ID:**
Address of School Corporation: 1501 Michigan
City: Gary **Zip:** 46402 **County Number:** 45
VIN: 4DRBUP1N0HB474347 **License Number:** 12632 **Bus Number:** 413
Make of Body: IC Corporation **Year:** 2016 **Make of Chassis:** IC Corporation **Year:** 2017
Bus Type: C **Mileage:** 80936
Inspection Status: R **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 46-1-5 | Upholstery or padding is ripped, torn, or improperly repaired |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.