

## REPORT OF SCHOOL BUS INSPECTION

|                                |                          |               |             |                  |              |
|--------------------------------|--------------------------|---------------|-------------|------------------|--------------|
| Type of Inspection:            | Re-Inspection            | Date:         | 9/4/2025    | Time:            | 9:45 AM      |
| Name of School Corporation:    | PROVIDENCE CRISTO REY    |               |             | Corp ID:         |              |
| Address of School Corporation: | 2717 S EAST STREET       |               |             |                  |              |
| City:                          | Indianapolis             | Zip:          | 46225       | County Number:   | 49           |
| VIN:                           | 4UZABRDT8FCFW9854        |               |             | License Number:  | S518541      |
| Make of Body:                  | Thomas Built Buses, Inc. | Year:         | 2015        | Make of Chassis: | Freightliner |
| Bus Type:                      | C                        |               |             | Mileage:         | 169073       |
| Inspection Status:             | O                        | Inspected By: | Kyle Parton | PE:              | 9108         |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 17-1-1                 | Any dome light is inoperative                                |
| 13-1-3                 | See Notes: Any defect inspector deems a violation not listed |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
| 63-2-3                 | Any tire is flat   |

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.