

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Spot Checks      **Date:** 9/17/2025      **Time:** 12:41 PM  
**Name of School Corporation:** AUXILIO SERVICES (MUNCIE)      **Corp ID:** 251807  
**Address of School Corporation:** 11260 Cornell Park Dr Suite 700  
**City:** Cincinnati      **Zip:** 45242      **County Number:** 18  
**VIN:** 4DRBUC8N7JB043637      **License Number:** B443U      **Bus Number:** M31  
**Make of Body:** IC Corporation **Year:** 2017      **Make of Chassis:** IC Corporation **Year:** 2017  
**Bus Type:** C      **Mileage:** 66820  
**Inspection Status:** R      **Inspected By:** Steve Spallinger      **PE:** 6921

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-2	Any seat back or bottom is loose

## Violations - Out of Service

## Inspection Code Description

### Bus Type Description

**Type C School Bus** - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.