

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 9/23/2025 Time: 10:36 AM
Name of School Corporation: SOUTHWEST PARKE COMM SCH CORP Corp ID: 616260
Address of School Corporation: RR 1
City: Montezuma Zip: 47862 County Number: 61
VIN: 1GB3G2BG4E1136376 License Number: 25343 Bus Number: SWP8
Make of Body: Chevrolet Year: 2013 Make of Chassis: Chevrolet Year: 2014
Bus Type: A1 Mileage: 79076
Inspection Status: O Inspected By: Tyler VanNess PE: 7583

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-10	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.