REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	9/23/2025	**Time:**	10:36 AM
Name of School Corporation:	SOUTHWEST PARKE COMM SCH CORP			**Corp ID:**	616260
Address of School Corporation:	RR 1				
City:	Montezuma	**Zip:**	47862	**County Number:**	61
VIN:	1GB3G2BG4E1136376	**License Number:**	25343	**Bus Number:**	SWP8
Make of Body:	Chevrolet **Year:** 2013	**Make of Chassis:**	Chevrolet	**Year:**	2014
Bus Type:	A1	**Mileage:**	79076		
Inspection Status:	O	**Inspected By:**	Tyler VanNess	**PE:**	7583

Violations - Rejected

Inspection Code	Description
20-1-10	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**