

# REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	9/23/2025	<b>Time:</b>	10:56 AM		
<b>Name of School Corporation:</b>	NORTH DAVIESS CO. COMM. SCHOOL			<b>Corp ID:</b>	141375		
<b>Address of School Corporation:</b>	5494 E SR 58						
<b>City:</b>	Elnora	<b>Zip:</b>	47529	<b>County Number:</b>	14		
<b>VIN:</b>	4UZABRDT6ECFS3096	<b>License Number:</b>	T462228	<b>Bus Number:</b>	16		
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2013	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2014
<b>Bus Type:</b>	C	<b>Mileage:</b>	114719				
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Philip Lubbers	<b>PE:</b>	7703		

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-4	Any front turn signal does not function properly
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
57-1-5	Step-well light is missing or inoperative

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

## Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**