

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	9/24/2025	Time:	9:04 AM		
Name of School Corporation:	SHELBY EASTERN SCHOOLS			Corp ID:	737285		
Address of School Corporation:	2451 N 600 E						
City:	Shelbyville	Zip:	46176	County Number:	73		
VIN:	1FSFE4FS1CDA29172		License Number:	E301299	Bus Number:	38	
Make of Body:	Girardin Minibus, Inc.	Year:	2013	Make of Chassis:	Ford	Year:	2011
Bus Type:	A2			Mileage:	64421		
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665		

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
46-1-3	Any required padding is missing

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.