

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|-------------------------|------------------------|-----------------|-------------------------|---------|
| Type of Inspection: | Spot Checks | Date: | 10/8/2025 | Time: | 3:06 PM |
| Name of School Corporation: | SETON CATHOLIC SCHOOL | Corp ID: | D842 | | |
| Address of School Corporation: | 233 South 5th Street | | | | |
| City: | Richmond | Zip: | 47374 | County Number: | 89 |
| VIN: | 1FDDR5PG2PKA64414 | License Number: | B302W | Bus Number: | 3 |
| Make of Body: | Collins Bus Corporation | Year: | 2023 | Make of Chassis: | Ford |
| Bus Type: | A1 | Mileage: | 11609 | Year: | 2023 |
| Inspection Status: | A | Inspected By: | Brandon Steffee | PE: | 8247 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.