

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	10/10/2025	Time:	10:53 AM
Name of School Corporation:	WHITLEY CO. CONSOLIDATED SCHLS			Corp ID:	928665
Address of School Corporation:	107 N Walnut St.				
City:	Columbia City	Zip:	46725	County Number:	92
VIN:	1T7Y84D23P1204703	License Number:	25876	Bus Number:	45
Make of Body:	Thomas Built Buses, Inc.	Year:	2022	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D			Mileage:	43835
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
34-1-1	Any headlight is inoperative
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.