

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/10/2025	Time:	11:43 AM		
Name of School Corporation:	NORTHWESTERN SCHOOL CORP.		Corp ID:	343470			
Address of School Corporation:	3075 N Washington St						
City:	Kokomo	Zip:	46901	County Number:	34		
VIN:	1BABNCSAXJF339729	License Number:		15723	Bus Number:	19	
Make of Body:	Blue Bird Corporation	Year:	2017	Make of Chassis:	Blue Bird Corporation	Year:	2018
Bus Type:	D	Mileage:		134793			
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
33-1-2	The grill is missing
7-1-2	ABS warning light is illuminated
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
11-1-1	The front bumper does not extend to the edge of the fenders
23-1-1	Any part is missing, including originally equipped heat shields
68-1-3	Reservoir is empty
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
34-1-5	See Notes: Any defect inspector deems a violation not listed
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
55-2-1	There is lateral steering shaft movement
55-2-3	Any steering component jams or inhibits safe movement
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
32-2-1	There is fuel leaking from any point on in the fuel system
51-2-1	The service door does not open or close properly
39-2-1	Inner fenders are loose from body or mounting brackets

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.

