

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	10/15/2025	Time:	10:39 AM
Name of School Corporation:	LOST RIVER CAREER CO-OP			Corp ID:	596150
Address of School Corporation:	610 Elm St Ste 1				
City:	Paoli	Zip:	57454	County Number:	59
VIN:	1G3HG31F521125340			License Number:	NBLRC1
Make of Body:	Blue Bird Corporation	Year:	2002	Make of Chassis:	Chevrolet
Bus Type:	A1			Mileage:	75901
Inspection Status:	O	Inspected By:	Philip Lubbers	PE:	7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
30-1-2	There are weak areas due to deterioration

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.